



PRESS PAD INSTRUCTIONS

These Press Pads are specially constructed to steam up and dry faster. For optimal performance, please follow the instructions below.

STEP 1:

Center pad on buck.

STEP 2:

Close press head and lock.

STEP 3:

Pull skirt of pad down towards the bottom of the press.

STEP 4:

Pull draw cord tightly and slip cord lock into place.

STEP 5:

Smooth out all wrinkles in skirt.

STEP 6:

Pull draw cord tightly a second time. Slip cord lock into place and tie a knot.

STEP 7:

Release head.

STEP 8:

Hook attached springs to the skirt.